



"Sharing incident learnings amongst ASI member companies"

"A vision of a safer steel industry"

Number: SA0008

Subject: Beam Bundle Pushed off Trailer

Date:(mth/yr) April 2005

Incident: (Brief facts only, do not include company name or location, insert picture if available)

- A forklift driver was moving a load of beams back to the centre of a trailer when the forklift tynes did not connect with the back of a bundle. The tynes pushed the back bundle off the opposite side of the trailer.
- Although there was minor product damage to a beam, people in the vicinity had maintained adherence to the exclusion zones, therefore no injuries resulted when product fell.

Key Lessons: (maximum of 3)

- Keeping a safe distance and performing the task effectively
- Communication between forklift driver and spotter
- Insufficient training for new employee around load awareness

Recommendations: (maximum of 3)

- Implement load barricading on opposite side of the trailer to avoid loss of product when loading
- Further formal and observation training required for employee, eg load restraint, awareness training
- Employee to review all current procedures for loading

For further information please contact **Ian Cairns** – National Safety Group Co-ordinator: ianc@steel.org.au

^{***} Safety Alerts are distributed by Australian Steel Institute as general information ONLY and are not intended as specific recommendations or advice ***